

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

669  
ENE  
1/2-1  
0.969 mi.  
5114 ft.

DOCTOR PRIME  
861 AV Z  
NYC, NY

NY Spills S102142335  
N/A

Relative:  
Higher

Actual:  
11 ft.

SPILLS:

Name: DOCTOR PRIME  
Address: 861 AV Z  
City,State,Zip: NYC, NY  
Spill Number/Closed Date: 8805530 / 1995-03-16  
Facility ID: 8805530  
Facility Type: ER  
DER Facility ID: 189324  
Site ID: 229668  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: D4  
SWIS: 2401  
Spill Date: 1987-10-29  
Investigator: DEANGELIS  
Referred To: Not reported  
  
Reported to Dept: 1988-09-29  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Citizen  
Cleanup Ceased: 1995-03-16  
Cleanup Meets Std: True  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1988-09-29  
Spill Record Last Update: 1995-03-16  
Spiller Name: Not reported  
Spiller Company: SAME  
Spiller Address: Not reported  
Spiller Company: 001  
Contact Name: Not reported  
DEC Memo: ""  
Remarks: "PILE OF MEDICAL WASTE - ANIMALS GETTING INTO IT. CERRY - ANSWERING SERVICE"

All Materials:

Site ID: 229668  
Operable Unit ID: 920698  
Operable Unit: 01  
Material ID: 457432  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: Not reported  
Recovered: .00  
Oxygenate: Not reported  
  
Site ID: 229668  
Operable Unit ID: 920698

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Operable Unit: 01  
Material ID: 457433  
Material Code: 0053A  
Material Name: medical waste  
Case No.: Not reported  
Material FA: Other  
Quantity: .00  
Units: Not reported  
Recovered: .00  
Oxygenate: Not reported